

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN NO.	5674	DATE	June 26 ,2025
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	On certain rearview mirrors, due to improper design dimensions, (1) The radius of the left rearview mirror curvature may be small. (2) The width of the interior rearview mirror (convex mirror) may be small. Therefore, they may result in not conforming to the structural requirements for one-man buses.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QRG-RU1ASCJ□ QTG-RU1ASCJ	[ISUZU GALA]	2012-2017	445
2PG-RU1ASDJ		2017-2024	305
QPG-RU1ESBJ□ QRG-RU1ESBJ		2012-2017	45
2KG-RU1ESDJ□ 2PG-RU1ESDJ		2017-2021	59
2DG-RU2AHDJ□ 2KG-RU2AHDJ		2017-2024	20
SDG-RU8JHBJ		2012-2017	53
		TOTAL	927