

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5676	DATE	Jun.26 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some vehicles, the effective dimension of the interior rearview mirror (convex mirror) is less than 300 mm, due to insufficient design review. This may conflict with the structural requirements of driver-only buses.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-MP37TK	「FUSO AERO STAR」	2010～2010	2
BJG-MP37TM		2010	1
PKG-MP35UM		2010～2010	5
LKG-MP35FK		2010～2012	10
LKG-MP35FM		2010～2012	70
LKG-MP35FP		2010～2012	6
LKG-MP37FK		2010～2012	53
LKG-MP37FM		2010～2012	8
TKG-MK27FH	「FUSO AERO MIDI」	2012～2017	84
QDG-MP35FM	「FUSO AERO STAR」	2012	1
QDG-MP35FP		2013～2014	2
QKG-MP35FK		2012～2017	3
QKG-MP35FM		2012～2017	121
QKG-MP35FP		2012～2017	36
QKG-MP37FK		2012～2014	86
QKG-MP37FM		2012～2015	60
QKG-MP38FK		2014～2017	78
QKG-MP38FM		2014～2017	100
QRG-MS96VP	「FUSO AERO ACE」	2012～2015	447
QTG-MS96VP		2015～2017	373
2KG-MP35FK	「FUSO AERO STAR」	2018～2022	9
2KG-MP35FM		2018～2023	27
2KG-MP35FP		2019～2024	22
2KG-MP38FK		2020～2022	3
2PG-MP35FK		2018～2024	7
2PG-MP35FM		2017～2024	83
2PG-MP35FP		2017～2024	48
2PG-MP38FK		2017～2024	275
2PG-MP38FM		2018～2024	196
2TG-MS06GP	「FUSO AERO ACE」	2017～2015	802

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-AP37FK	「SPACERUNNER A」	2010~2010	3
LKG-AP35FM		2010~2010	3
		TOTAL	3,024