

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5677	DATE	Jun. 26. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	Some interior rearview mirrors (convex mirrors) have a smaller mirror surface width due to the inappropriate dimensional control in the manufacturing process. Therefore, the mirror surface width of interior rearview mirrors may not comply with the structural requirements for one-man buses, buses without a conductor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-KR290J1	[HINO Rainbow]	2012~2016	75
SKG-KR290J1			
SKG-KR290J2		2016~2017	143
2KG-KR290J3		2017~2019	245
2KG-KR290J4		2019~2023	320
2KG-KR290J5		2023~2024	79
QKG-KV234L3	[HINO Blue Ribbon II]	2012~2013	3
QKG-KV234N3		2012~2015	121
QPG-KV234N3			
QKG-KV234Q3		2013~2017	10
QPG-KV234Q3			
QDG-KV290N1	[HINO Blue Ribbon]	2015~2017	95
QKG-KV290N1			
2DG-KV290N2		2017~2019	68
2KG-KV290N2			
2TG-KV290N2			
2DG-KV290N3		2019~2023	90
2KG-KV290N3			
2TG-KV290N3			
2KG-KV290N4		2023~2024	16
QKG-KV290Q1		2015~2017	203
QPG-KV290Q1			
QRG-KV290Q1			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-KV290Q2	[HINO Blue Ribbon]	2017～2019	138
2PG-KV290Q2			
2TG-KV290Q2			
2PG-KV290Q3		2019～2023	130
2RG-KV290Q3			
2TG-KV290Q3			
2KG-KV290Q4		2023～2024	42
2RG-KV290Q4			
2TG-KV290Q4			
KX525Z1	[-]	2020	1
QSG-HL2ANAP	[HINO Blue Ribbon Hybrid]	2015～2017	4
2SG-HL2ANBP		2017～2024	39
QSG-HL2ASAP		2015～2017	21
2SG-HL2ASBP		2017～2023	24
		TOTAL	1, 867

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
rearview mirrors	4-63511147-0	2012～2024	53
rearview mirrors	KX24550019	2012～2022	14
		TOTAL	67