

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5678	DATE	Jun. 26. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain rearview mirrors, due to improper design dimensions,</p> <p>① The radius of the left rearview mirror curvature may be small.</p> <p>② The width of the interior rearview mirror (convex mirror) may be small.</p> <p>Therefore, they may result in not conforming to the structural requirements for one-man buses.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
QQG-RU1ASBR	[HINO Selega]	2013～2016	22	①22 ②0
QRG-RU1ASCA		2012～2017	513	①513 ②2
QTG-RU1ASCA				
2PG-RU1ASDA		2017～2024	431	①431 ②0
QPG-RU1ESBA		2012～2017	272	①272 ②0
QRG-RU1ESBA				
2KG-RU1ESDA		2017～2020	116	①116 ②2
2PG-RU1ESDA				
2DG-RU2AHDA		2017～2024	58	①58 ②4
2KG-RU2AHDA				
LDG-RU8JHBA		2012～2017	52	①52 ②6
SDG-RU8JHBA				
SDG-HX9JHBE	[HINO Poncho]	2013～2017	35	①0 ②35
SKG-HX9JHBE				
2DG-HX9JHCE		2017～2024	155	①0 ②155
SDG-HX9JLBE		2012～2017	215	①0 ②215
SKG-HX9JLBE				
2DG-HX9JLCE		2018～2024	532	①0 ②532
		TOTAL	2, 401	①1, 464 ②951

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
rearview mirrors	KK101037AA	2012～2025	125
		TOTAL	125