

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5683	DATE	June. 26. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some front tires come with a carcass inside the tire, which is not molded at a proper angle due to the improper tire manufacturing process. For this reason, if the vehicle continues high-load operation such as high-speed running, stress concentrates on the carcass and the cords are broken, causing cracks on the inner surface of the tire and distorting the tire tread. This has the risk of causing the vehicle body to shake, spoiling driving stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RH09	「NC750X」	2024	284
		TOTAL	284