

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5679	DATE	2. Jul.. 2025
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the interior part material of the seat cushion and the backrest of the seat, the selection of material for the waterproof film that is used under the seat cover and for some polyurethane material was not suitable. As the result, the subject parts burn faster than the rate of burning specified in the flammability test and therefore do not meet the safety standards for road vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ASSEMBLED	AR-04	2014~2021	19
PROTOTYPE	AR-04	2021~2024	19
ASSEMBLED	APP	2018~2021	5
ASSEMBLED	AR-05	2019~2021	7
PROTOTYPE	AR-05	2021~2025	9
ASSEMBLED	AR-07	2017~2021	56
PROTOTYPE	AR-07	2021~2025	80
ASSEMBLED	YG-M	2017~2019	6
ASSEMBLED	YG-M FCV	2019	1
ASSEMBLED	YG-ML	2018~2020	14
ASSEMBLED	YG-ML+	2018	1
ASSEMBLED	AGILE	2020	1
ASSEMBLED	CY-1	2018	2
TOTAL			220