

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5682	DATE	3 July, 2025
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	Some cooling systems for agricultural tractors have insufficient fastening force due to improper assembly of the cooling water drain hose. Therefore, if the tractor continues to be used in this condition, the cooling water drain hose may pull out from the pin, causing the cooling water to leak, and in the worst case, the engine may stop.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GT25J	「XN18」	2024,2025	41
	「XS18」	2024,2025	27
	「XS20」	2024,2025	75
	「XS23」	2024,2025	92
	「XS25」	2024,2025	125
		TOTAL	360