

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5689	DATE	July 11, 2025
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	About the left crops guide of combine, due to an improper manufacturing method, some dimensions of left crops guide exceed the design values, and when installed on the machine, the vehicle width may exceed 1,700 mm. This combine not install lighting equipment for vehicle exceed width 1,700mm and have a risk of violating the safety standards.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C237	KR217	31/7/2024~9/4/2025	160
C236	KR220	29/7/2024~31/3/2025	146
		TOTAL	306