

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5703	DATE	July. 16. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for a removable, portable battery that is mounted on an electric motorcycle, due to the inappropriate welding conditions of the cell and components in the battery, sometimes the cell is damaged, causing an electrolyte leakage. For this reason, if the vehicle continues to be used, there is a risk of metal precipitation because of the leaked electrolyte, which can cause a short circuit. This may result in the cell catching fire, leading to a vehicle fire eventually.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAD-EF07	「BENLY e I 」	2021～2023	19,279
ZAD-EF08	「BENLY e I PRO」		
ZAD-EF09	「BENLY e I MD」		
ZAD-EF10	「BENLY e II 」		
ZAD-EF11	「BENLY e II PRO」		
ZAD-EF12	「BENLY e II MD」		
ZAD-EF13	「GYRO e:」		
ZAD-EF14	「GYRO CANOPY e:」		
ZAD-EF16	「EM1 e:」		
ZAD-EF18	「CUV e:」		
		TOTAL	19,279