VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5702	DATE	Jul. 30. 2025	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	On certain starter electrical wiring, due to insufficient design consideration of wiring variance, some of the wiring is interfering with the edge of the cross member. Therefore, if it continues to be used as is, the insulation of the wiring may be damaged by vibrations while driving. And in the worst case, the wiring may short circuit, causing a fire.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FN1AJA	[HINO Profia]	2017~2025	2, 818
2DG-FN1AJC			
2DG-FN1AJE			
2DG-FN1AJG			
2KG-FN1AJG			
2DG-FN1AGA		2018~2021	9
		TOTAL	2, 827