

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5706	DATE	Aug.26 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>A flame-retardant material is not added to the sun visor surface which is made from nonwoven PVC. Therefore, it burns faster than the rate specified in the standard on the burn test and does not meet the safety standard.</p> <p>( PVC : polyvinyl chloride)</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HJR	「FUSO SUPER GREAT」	2022~2024	11
2KG-FV70HYP		2022~2023	8
2KG-FV70HZP		2022~2023	3
2KG-FV74HJR		2022~2023	6
2PG-FP74HDR		2022~2024	80
2PG-FP74HER		2022~2024	39
2PG-FP74HGR		2023	1
2PG-FS70HZ		2022~2023	20
2PG-FS74GZ		2023	1
2PG-FS74HZ		2022~2023	65
2PG-FS75HZ		2022~2023	49
2PG-FU70HY		2023~2023	2
2PG-FU74GY		2023	1
2PG-FU74GZ		2022~2023	2
2PG-FU74HY		2023	1
2PG-FU74HZ		2022~2024	32
2PG-FU75HZ		2022~2023	23
2PG-FV70GX		2023~2023	2
2PG-FV70GY		2022	1
2PG-FV70HX		2022~2024	118
2PG-FV70HY		2022~2024	41
2PG-FV70HZ		2022~2024	31
2PG-FV74HJR		2023~2023	2
2PG-FV74HZ		2022~2023	14
2PG-FY70HY		2023~2023	3
2PG-FY74HY		2023~2023	2
		TOTAL	558

The affected parts shipped as repair parts, but the vehicle with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
SUNVISOR, RH, STANDARD	ML249106	2023~2023	2
SUNVISOR, RH, STANDARD	MC967992	2023~2023	2
SUNVISOR, RH, STANDARD	ML231372	2022~2023	14
SUNVISOR, CTR, STANDARD	MK565402	2022~2024	20
SUNVISOR, LH, STANDARD	MK565403	2022~2024	87
SUNVISOR, RH, HIGH ROOF	ML231374	2022~2023	7
SUNVISOR, RH, HIGH ROOF	MC966128	2023~2023	2
SUNVISOR, CTR, HIGH ROOF	MK565406	2022~2024	8
SUNVISOR, LH, HIGH ROOF	MK565407	2022~2024	63
SUNVISOR, LH, HIGH ROOF	MC936840	2023~2023	2
		TOTAL	207