

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5711	DATE	September.4.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the air conditioning system of the subject vehicles, due to insufficient consideration of the program, in the event of a specific failure diagnostic code of the air conditioning components is detected, there is a possibility that heater may not operate for an excessive fail-safe control. In this condition, the defrosting performance reduces and may not remove frost and/or fog from the windshield glass.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
ZAA-XEAM10	[bZ4X]	2022-2025	1,650	
ZAA-YEAM15			905	
ZAA-XEBM15	[RZ450e]	2023-2025	1,848	
ZAA-XEBM10	[RZ300e]		389	
ZAA-XEAM10X	[SOLTERRA]	2022-2025	187	
ZAA-YEAM15X			1,146	
		TOTAL	6,125	