

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5709	DATE	SEPTEMBER 9 , 2025
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	The anti-entrapment device for anti-freeze spraying vehicles is not strong enough due to insufficient design considerations. Therefore, if it continues to be used as is, there is a risk that it will be damaged by vibrations caused by driving.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-CW5YL	Quon	2015 CW5YL-30379, CW5YL-30382	2
		2017 JNCMM60D3HU021760	1
2PG-CW5BL		2018～2022 JNCMB02D0JU035881～JNCMB02D2NU070590	104
2PG-CW5EL		2023～2024 JNCMCH0D6PU082095～JNCMCH0D1RU090141	10
		TOTAL	117

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.