

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5718	DATE	September.17.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front and side cameras of panoramic view monitors, cracks could have developed inside the camera circuit elements due to insufficient consideration of the manufacturing process. Therefore, cracks expand over time and cause poor continuity. In this condition, the image of left side of the vehicle is unable to confirm, which would not meet applicable requirement of “Safety Regulations for Road Vehicles”.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-MXPB10	[YARIS CROSS]	2022-2024	9,530	
5BA-MXPB15			2,580	
6AA-MXPJ10			39,201	
6AA-MXPJ15			8,570	
3BA-ZSG10	[COROLLA CROSS]	2022-2023	8,488	
6AA-ZVG11			23,344	
6AA-ZVG15			7,071	
		TOTAL	98,784	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-ZVG15	[COROLLA CROSS]	2022	1	
		TOTAL	1	

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Television camera ASSY front	86790-52291	2023-2024	580	[YARIS CROSS]
Television camera ASSY side LH	86790-52441		568	
Television camera ASSY side RH	86790-52451		506	
Television camera ASSY front	86790-16031		215	[COROLLA CROSS]
Television camera ASSY side LH	86790-16041		199	
Television camera ASSY side RH	86790-16051		442	
Outer Rr view mirror ASSY RH	87910-52J41	2022-2025	60	[YARIS CROSS]
	87910-52J51		274	
Outer Rr view mirror ASSY LH	87940-52J01		61	
	87940-52J11		281	
Outer Rr view mirror ASSY RH	87910-16A01		323	
Outer Rr view mirror ASSY LH	87940-16A01		365	
		TOTAL	3,874	