

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5723	DATE	Oct.9 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>In some manually foldable left-side mirrors, due to an insufficient consideration of the evaluation method, cracks may occur in the unit flange of the manually foldable unit, such as those caused by vibrations during driving. If the vehicle continues to be used in this condition, the cracks will progress, and the mirror may fall off in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MS96JP	「FUSO AERO ACE」	2007～2010	379
	「FUSO AERO QUEEN」	2007～2010	11
LKG-MS96VP	「FUSO AERO ACE」	2010～2012	123
PDG-MM96FH		2008～2011	7
SDG-MM96FH		2011	1
QDG-MM97FH		2014	1
QRG-MS96VP		2012～2015	349
		「FUSO AERO QUEEN」	2012～2015
QTG-MS96VP	「FUSO AERO ACE」	2015～2017	211
	「FUSO AERO QUEEN」	2015～2017	8
PDG-AM96FH	「SPACERARROW A」	2009	1
BKG-AS96JP		2008～2009	12
		2010～2010	5
		TOTAL	1,121