

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5726	DATE	Oct 23, 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	In the engine control module, because the program is inappropriate, there is a possibility that the exhaust gas value at the time of engine misfire exceeds the regulation value and the vehicle does not meet the safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-EF11M	V-STROM	2025	45
		TOTAL	45