

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5729	DATE	October. 23. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some gear change pedals have excessively coated pivot bolt bearing surfaces due to inappropriate instructions on coating the surface. Because of this, if the coating deforms due to the heat of the catalytic converter on the exhaust pipe, the said bolt will come loose, and as the gear shift operation is repeated, the bolt may fall out and the change pedal may come off, which would disable the gear shift operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-SC86	「CB1000 HORNET」 「CB1000 HORNET SP」	2024～2025	622
TOTAL			622