

VEHICLE SAFETY／POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5725	DATE	2025/12/05
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	<p>Due to inappropriate weld leg length on the front frame parts where the snow removal device is mounted on the rotary snowplow, part of the front frame may be damaged. In the worst case, the snow removal device may detach, resulting in inability to operate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-NR6B	NR303 Rotary Snow Plow	2024	34
YDS-NR7B	NR403 Rotary Snow Plow	2024	2
TOTAL			36