

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5756	DATE	December 23, 2025
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Some nuts at the fastening point between the steering wheel and the steering column of the shovel loader are not tightened to the specified torque, due to inappropriate work instructions. As a result, the nuts may loosen due to steering and other operational inputs, which may cause play in the steering wheel during operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-WA139	「WA80-8」	2025	9
YDP-WA138	「WA100-8」	2025	17
YDP-WA138	「WA150-8」	2025	3
YDR-WA137	「WA200-8」	2025	5
YDR-WA136	「WA270-8」	2025	1
YDR-WA135	「WA320-8」	2025	1
TOTAL			36