

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5740	DATE	2026/1/14
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO., LTD.		
DESCRIPTION OF DEFECT	<p>The front, rear, and side windows of the shovel loader exhibit weak adhesion due to the use of an incorrect primer. As a result, adhesion may deteriorate over time, causing the bond to fail. This could allow rainwater or other liquids to enter the vehicle interior, and in the worst case, the glass may detach.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-V37	「V3-7」	2023 to 2024	64
V37E	「V3-7S」	2023 to 2024	60
YDM-V47	「V4-7」	2023 to 2024	63
YDM-V57	「V5-7」	2023 to 2024	9
YDM-RW06	「LK40Z-6」	2023 to 2024	5
RV06	「LK40ZST-6」	2023 to 2024	2
YDM-RX06	「LK50Z-6」	2023 to 2024	26
TOTAL			229

(日本工業規格A列4番)