

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5746	DATE	January 13,2026
MUNUFACTURER	HOWA MACHINERY,LTD.		
DESCRIPTION OF DEFECT	<p>In the hydraulic circuit of the cleaning vehicle's working equipment, the check valve is not properly selected, and the heat from the engine etc. can cause the pressure in the piping to rise. As a result, the check valve of the working equipment does not open due to the pressure, and the cleaning equipment (left and right brushes and hood) cannot be retracted after the working equipment has stopped, which may cause interference with other traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NMR88M	「ELF」	2023~2025	20
		TOTAL	20