

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5761	DATE	January. 13. 2026
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the on-board diagnostic (OBD) systems, due to insufficient consideration of the engine control unit program, the calculated load value when the engine is stopped is not displayed correctly on the diagnostic scan tool. Because of this, the products do not conform to the safety standards for road vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BJ-RE46J	XSR125	2023~2025	4,709
8BJ-RE45J	YZF-R125 MT-125	2023~2024	2,118
8BK-RG86J	YZF-R15	2023	844
		TOTAL	7,671