

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5762	DATE	January.14.2026
MANUFACTURER	TOYOTA AUTO BODY CO.,LTD.		
DESCRIPTION OF DEFECT	Due to insufficient design review of the “CABLE ASSY, PARKING BRAKE”, stress may occur near the crimped section of the cable. Repeated operation of the parking brake may cause the cable to break. In the worst case, the parking brake may fail, potentially allowing the vehicle to move.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TAK30	COMS	2012~2021	8,536
TOTAL			8,536