

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5766	DATE	January.14.2026
MANUFACTURER	TOYOTA AUTO BODY CO.,LTD.		
DESCRIPTION OF DEFECT	Due to an improper charging control program in the “CHARGER ASSY, ELECTRIC VEHICLE”, overcharging may occur. Repeated overcharging may accelerate deterioration of the inter-cell connections within the “BATTERY ASSY, ELECTRIC VEHICLE”. This could cause an internal break in the battery, resulting in loss of power. In the worst case, this may lead to loss of mobility while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TAK30	COMS	2012~2025	11,752
		TOTAL	11,752