

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 7 6 9	DATE	February 6, 2026
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper manufacturing control, some rotary snowplows have had bearings of different quality installed in the intermediate shaft between the engine and transmission. As a result, grease leaks from the bearing's oil supply hole, resulting in insufficient lubrication. If the vehicle continues to be used in this state, it can wear abnormally, and in the worst case scenario, the bearing may break and become unable to run.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03F	HTR308A	2025	4
		TOTAL	4