

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5777	DATE	Feb.18.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In an automatic transmission of the subject vehicles, due to insufficient consideration of the control program, the program may not prevent the transmission from over-revving when a transmission component failure occurs. In this condition, the transmission could be damaged leading to a loss of motive power, and in the worst case, transmission fluid could leak and contact exhaust components, resulting in a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3DA-FJA300W	[LAND CRUISER]	2025	2,598	
3BA-VJA300W			5,875	
3BA-VJA310W	[LX600]		1,354	
		TOTAL	9,827	