

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5779	DATE	February 25, 2026
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	<p>Following two conditions are identified with forklifts registered as small-sized special motor vehicles:</p> <p>① Due to inappropriate design instructions for rear position lamps, stop lamps and reversing lamps, some vehicles with overall height exceeding 2.0 m are not equipped with rear position lamps, stop lamps or reversing lamps. As a result, there is a possibility that such vehicle does not comply with safety standards.</p> <p>② Due to insufficient design consideration of rear reflex reflectors, in some cases, distance from outermost edge of vehicle to outermost edge of rear reflex reflector exceeds 400 mm. As a result, there is a possibility that such vehicle does not comply with safety standards.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
3FBK5	TOYOTA FORKLIFT	2001 - 2002	2	②
ZAF - A3FBK5		2016 - 2021	2	②
		2012	1	①
3FBK9		1996 - 2004	8	②
ZAF - A3FBK9		2006 - 2023	20	②
		2021 - 2024	2	①
3FB9		1996 - 2006	394	①
ZAF - A3FB9		2006 - 2025	630	①
3FG9		1997 - 2008	279	①
403FG9		1997 - 2008	862	①
A3FG9		2008 - 2025	389	①
			TOTAL	2,589