

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	5782	DATE	March,17,2026
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO.,LTD (JAPAN)		
DESCRIPTION OF DEFECT	<p>Some hydraulic pumps for moving tire rollers have improperly machined internal components. As a result, the wear of the parts tends to progress, and the parts may fall off due to excessive wear. In the worst case, the dropped parts may damage the internal mechanism, prevent the parking brake from being released, and make it impossible to drive.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF	REMARKS
KDP-CP220	「CP220-3」	2009~2013	168	
KDP-N22A2	「HN220WHH-2」	2011~2012	7	
WDP-TAB	「ZC220P-5」	2014~2014	13	
3 models in total	3 models in total	2009~2014	Total 188	