

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5785	DATE	25 Mar, 2026
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In the main shift lever of a reaping and threshing work vehicle, an excessive load may be applied to the main shift lever fulcrum because the design of the fulcrum and disc spring is insufficient. Therefore, if you continue to use the vehicle as it is, it will become difficult to operate the gear shift lever, and in the worst case, the welded part of the lever fulcrum may break and come off, making it impossible to drive.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-VC65B	「V465」	2022~2023	61
	「V565」	2022~2023	20
YDN-VC75C	「V475A」	2022~2023	24
	「V575A」	2022~2024	85
YDN-VC75D	「VCH750A」	2022~2023	38
		TOTAL	228