

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5790	DATE	Apr.8.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the tire pressure monitoring system of the subject vehicles, due to incorrect program of the system error detection, if a system error occurs and the vehicle continues to drive at low speed, it will take longer time to detect the error. In this condition, the tire pressure warning light may be delayed in illuminating.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
shisaku	[e-palette]	2025-2026	42	experimental car
TOTAL			42	