

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 7 9 2	DATE	Apr. 9. 2026
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the recall campaign of Notification No. "5485" dated May 30, 2024, the front fixing bolts of the front suspension members were tightened by more than the specified torque due to improper description in the operation manual for replacing the drive motor.</p> <p>Therefore, the bolt may be slightly extended and loosened due to vibration or the like during driving, and in the worst case, a gap may be created between the front suspension member and the vehicle body frame, and abnormal noise may be generated due to interference.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-FE0	ARIYA	2022~2023	65
		TOTAL	65