

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5804	DATE	April 24, 2026
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>In the grader's steering post, insufficient design consideration of the gas spring that holds the steering post may cause gas inside the spring to leak when the tilt pedal is operated.</p> <p>As a result, continued use may lead to a reduction in the holding force of the gas spring, making it impossible to fix the steering wheel at a desired position. In the worst case, there is a risk that steering operation may no longer be performed reliably.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-GD035	GD405-7	2019-2026	731
		TOTAL	731