

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5814	DATE	April 24 ,2026
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>Due to insufficient design consideration of the seat suspension under the driver's seat, when raising the seat after the battery terminal is disconnected, the suspension may remain locked and become unable to release, making the seat height unable to be adjusted. If the vehicle continues to be used under these conditions, vibrations from driving may unexpectedly release the suspension lock and cause the seat to rise, and the suspension lock may not operate properly.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-CXZ77DT	[GIGA]	2025	1
2PG-CYJ77D□ 2PG-CYJ77DA		2025	14
2PG-CYL77D		2025	6
2PG-CYY77DU		2025	1
2RG-FRR90S4	[FORWARD]	2025	3
2PG-FSR90T4		2025	1
2RG-FTR90V4		2025	3
		TOTAL	29