

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5809	DATE	April 28, 2026
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>①The control unit of the harvesting and threshing vehicle was equipped with a program that causes a work light on the top of the front windshield to flash when the grain tank (the part where harvested crops are stored) becomes full during harvesting. This function was intended to allow the assistant operator to visually determine when the tank was full, but since this flashing light is not included in the list of lights that are permitted on a vehicle, it violates safety standards.</p> <p>②The control unit of a harvesting and threshing vehicle equipped with an autonomous harvesting function, due to insufficient design considerations, a program was installed that automatically illuminates the reverse lights more than 3 seconds before reversing begins as a warning to the surroundings during autonomous operation. However, since these reverse lights automatically illuminate while the vehicle is moving forward, this violates safety standards.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-C524	DR575	2019~2025	544
YDP-C523	DR595	2018~2026	729
YDR-C615	DR6130	2018~2026	3048
YDR-C701	DR7130	2022~2025	197
		TOTAL	4518