

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5812	DATE	2026/5/8
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	Due to insufficient design considerations in the fuel system, the fuel pre-filter interferes with the rear fender rib. As a result, vehicle vibrations may damage the fuel pre-filter, and in the worst case, the filter may break and leak fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-NR6C	NR304 Rotary Snow Plow	2026	1
		TOTAL	1