

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5818	DATE	May. 14. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the motor power supply unit, the AC charging connector may be assembled with the terminal of an incorrect component due to the improper manufacturing process. This poses a risk of the poor connection of the terminal at the time of charging, preventing the AC charging. Also, since the tip of the terminal is not protected, it does not comply with the Safety Regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-ZC7	「Honda e」	2023	59
			TOTAL
			59