

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5813	DATE	May-15-2026
MANUFACTURER	PABCO CO.,LTD		
DESCRIPTION OF DEFECT	Due to insufficient verification of compliance with regulatory standards during the design stage of the side guard (underrun protection device), the distance between the front edge of the right-side side guard flat section and the rear edge of the right front wheel exceeds 400 mm, resulting in non-compliance with safety regulations.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FRR90S4	FORWARD	2024 ~ 2025	19
2RG-FRR90T4		2024	1
		TOTAL	20