

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5819	DATE	May 15, 2026
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the exhaust gas emission control device of shovel loaders, the ECU program is inappropriate the start conditions for stationary manual regeneration of the aftertreatment system from being met, thus making stationary regeneration impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	WA100-8 WA150-8	2026	80
TOTAL			80

The range of vehicles that may have been shipped and assembled with replacement repair parts.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	WA100-8 WA150-8	2020 – 2025	36
TOTAL			36