

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5799	DATE	17, 6, 2026
MANUFACTURER	Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the exhaust system of forklift trucks, inappropriate material selection and design specifications for the front tube have resulted in insufficient material strength and inadequate machining accuracy at the fastening section. As a result, the front tube may lack the required durability. Continued use in this condition may lead to damage to the front tube and a potential leakage of exhaust gas.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBT-J1F4	「J1F4」	2009 – 2024	6
EBT-JG1F4	「JG1F4」		5
EBT-F197	「H1F4」		10
EBT-F198	「HG1F4」		2
		TOTAL	23