

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 8 3 4	DATE	Jun. 26. 2026
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the lithium-ion battery controller, an unnecessary abnormality detection may occur due to an improper control program. As a result, an EV system warning message may be displayed on the combination meter, and the drive motor output may be limited. In the worst case, the output to the drive motor may be stopped while driving, and the vehicle may not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-E 1 3 6 AA-SNE 1 3	NOTE	2 0 2 0 ~ 2 0 2 6	3 2 2, 0 2 3
6 AA-FE 1 3 6 AA-FSNE 1 3	NOTE AURA	2 0 2 1 ~ 2 0 2 6	1 8 3, 8 2 8
6 AA-T 3 3 6 AA-SNT 3 3	X-TRAIL	2 0 2 2 ~ 2 0 2 6	9 4, 7 4 4
		TOTAL	6 0 0, 5 9 5