

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5835	DATE	June 29, 2026
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	In electric forklifts, due to inappropriate design instructions, driving headlights cannot be manually turned off immediately. As a result, the lighting equipment does not satisfy the technical standards for lamps as well as comply with the safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-8FB18	TOYOTA GENEIO-B	2019 - 2023	11
		TOTAL	11