

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5841	DATE	Jul. 1. 2026
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heat shields protecting the brake hoses, due to improper parts management, there are some lacking the necessary anti-corrosion treatment. Therefore, the heat shields may corrode during use. In the worst case, if a heat shield detaches, the heat from the exhaust pipe could damage the brake hose, allowing air to leak, causing a reduction in braking performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FC2ABA	[HINO Ranger]	2025	403
2KG-FC2ABG			
2PG-FC2ABA			
2PG-FC2ABG			
2KG-FD2ABA		2025	922
2KG-FD2ABG			
2KG-FD2ABJ			
2PG-FD2ABA			
2PG-FD2ABG			
2PG-FD2ABJ			
2KG-FE2ACA		2025	297
2KG-FE2ACG			
2PG-FE2ACA			
2PG-FE2ACG			
2KG-FJ2ACA		2025	89
2KG-FJ2ACG			
2PG-FJ2ACA			
2KG-FX2ABA		2025	29
2KG-GC2ABA		2025	94
2KG-GC2ABG			
2KG-GD2ABA		2025	122
2KG-GD2ABG			
2KG-GX2ABA		2025	24
2PG-GX2ABA			
		TOTAL	1, 980