

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 8 4 4	DATE	Jul. 23. 2026
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the final inspection at the vehicle manufacturing plant, due to inadequate management of the final inspection process, the tightening confirmation of the road wheel fastening parts has not been performed after conducting sampling evaluation involving wheel removal and installation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-E 1 3	NOTE	2 0 2 2 ~ 2 0 2 3	5
6 AA-FE 1 3	NOTE AURA	2 0 2 2 ~ 2 0 2 4	2
Z AA-ZE 1	LEAF	2 0 2 3	2
		TOTAL	9