

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5852	DATE	July 23, 2026
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	In the electromagnetic brake valve used on graders, the evaluation of heat resistance regarding the aging of the internal coil was insufficient during the electrical circuit design phase. Consequently, if heat-induced damage accumulates during operation, a partial short-circuit may occur within the coil, causing an increase in current through the electrical wiring; in the worst-case scenario, this could lead to the wiring burning out and rendering the vehicle inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-1ER13	ER555F	2017 — 2023	145
		TOTAL	145