

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5854	DATE	July. 30. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In some driver's seats or front passenger's seats, the ends of their left side frames are not correctly molded due to the inappropriate mold to form those frames and inappropriate manufacture management. For this reason, the shapes of the ends of those frames do not comply with the Safety Regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
6AA-RZ4	「ZR-V」	2025		7,186
6AA-RZ6				3,357
5BA-RZ3				281
5BA-RZ5				99
5BA-FL1	「CIVIC」			2,383
6AA-FL4				1,424
			TOTAL	14,730

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS "SERVICE PARTS"	NUMBER OF PARTS	NOTE
BACK FRAME ASSY R	81125-3V0-J51	2025~2026	57	「ZR-V」
BACK FRAME ASSY L	81525-T24-Z61	2025	4	
BACK FRAME ASSY R	81125-T50-J71		7	「CIVIC」
		TOTAL	68	