

KU-KEN-640

No.TCD -2950-88

Date June 15, 1988

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Kawasaki BK117 Series Helicopters: S/N 1001 through 1006 and 1008 through 1015

2. Compliance required as indicated, unless already accomplished.

To prevent possible stall of the main rotor blades, within 10 flight hours after the effective date of this AD, replace existing VNE placards (P/N 117-74105-01/03, 117-74107-01/03) with new placards (P/N 117-74108-01/03/05/07), and incorporate the applicable revision (Second Issue, Rev.4 for BK117, Original Issue, Rev.4 for BK117A-3, and Original Issue, Rev.3 for BK117A-4) dated March 31, 1988 into the Flight Manual in accordance with Kawasaki Service Bulletin KSB-117-045 dated May 31, 1988.

3. Remarks

3.1 This AD becomes effective on July 18, 1988.

3.2 Kawasaki Service Bulletin KSB-117-045 dated May 31, 1988 pertains to this subject.