

KU-KEN- 78

No.TCD- 631A-70

Date March 10, 1970

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: **FUJI Model FA-200 series airplanes**

2. Compliance required as indicated

To prevent a malfunction of the fuel quantity indicator due to failure of the transmitter, within the next 50 hours' time in service and thereafter at intervals not to exceed 50 hours' time in service, check and replace, as necessary, in accordance with FUJI HEAVY INDUSTRIES SERVICE BULLETIN No. FAS-005B or later JCAB-approved revisions.

3. Remarks

3.1 Effective date: March 10, 1970.

3.2 FUJI HEAVY INDUSTRIES SERVICE BULLETIN No. FAS-005B covers this subject.

3.2 This AD supersedes TCD-631-70.