

KU - KI - 552

No. TCD- 3393A - 96

Date May 14, 1996

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory

1. Applies to : Mitsubishi Heavy Industries (MHI) Model MU-2 series : S/N 8 through 347 (except S/N 313 and 321) and S/N 501 through 696 (except S/N 652 and 661)

2. Compliance required as indicated, unless already accomplished.

To ensure the operation of anti-ice/deice systems, accomplish the followings:

- 2.1 Within 10 flight hours after the effective date of this AD, inspect the anti-ice/deice systems, and replace or repair deficient system as necessary, in accordance with MHI MU-2 Service Bulletin No. 212A dated April 25, 1996, or its later JCAB-approved revisions (SB).
- 2.2 After the inspection described in paragraph 2.1 of this AD, repeat the inspection of the anti-ice/deice systems at intervals not to exceed 100 flight hours in accordance with SB.

3. Remarks

- 3.1 This AD becomes effective on June 1, 1996.
- 3.2 MHI MU-2 Service Bulletin No. 212A dated April 25, 1996 pertains to this subject.
- 3.3 This AD supersedes TCD-3393-91.