

KU-KEN-760

No.TCD - 2493 - 85

Date September 10, 1985

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to : NAMC Model YS-11/-11A series airplane

2. Compliance required as indicated, unless already accomplished.

To prevent the failure of the bolt attaching the vertical stabilizer front spar fitting on the fuselage, within 150 hours time in service after the effective date of this AD, inspect, and replace if required, the bolts (P/N MS 20010-32) for the front spar fittings (P/N 01-38101-11/12) in accordance with NAMC YS-11 Service Bulletin No. A53-69, dated September 10, 1985.

3. Remarks

3.1

This AD becomes effective on September 10, 1985.

3.2

NAMC YS-11 Service Bulletin No. A53-69, dated September 10, 1985, pertains to this subject.