

KU-KI-1482

No. TCD-4904-98

Date November 16, 1998

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory

1. Applies to : NAMC Model YS-11 and -11A series airplanes, serial number 2050 and subsequent, modified in accordance with NAMC Service Bulletin (SB) No.28-32 approved on July 19, 1978 or further JCAB approved revisions.

2. Compliance required as indicated, unless already accomplished.

To prevent the leakage of fuel due to cracking of scavenge pump pressure switch fuel sensing tube, accomplish the following.

2.1 Within 100 flight hours after the effective date of this AD, replace aluminum scavenge pump pressure switch fuel sensing tubes with CRES tubes in accordance with SB No.28-35 Rev.1 approved on November 4, 1998 or further JCAB approved

Japan Civil Aviation Bureau	No. TCD-4904-98	sheet 2/2
<p>revisions.</p> <p>2.2 An alternative means of compliance with this AD may be used, if approved by the Director-General of JCAB.</p>		
<p>3. Remarks</p> <p>3.1 This AD becomes effective on November 26, 1998.</p> <p>3.2 NAMC Service Bulletin No.28-32 approved on July 19, 1978 and No.28-35 Rev.1 approved on November 4, 1998, and further JCAB approved revisions pertain to this subject.</p>		